

DATE <u>1/17/55</u>	TMC SPECIFICATION NO. S- 249	
SH. <u>1</u> OF <u>1</u>		
COMPILED BY A.J.J.	TITLE: BALLAST REPLACEMENT IN MODEL PMO	JOB 313
APPROVED <u>A. J. J.</u>	Page Issue <u>A</u>	

SUBJECT: R102 (TMC # RR-109)

PURPOSE: Under certain field conditions the supply agency may experience temporary difficulty in obtaining replacement Ballast regulators for the Model PMO.

In this event, operation may be resumed by inserting any one of the following vacuum tubes in the same socket:

6BK7

6T8

6U8

In addition, in those units in which the R102 socket is not already wired so, pin 2 must be shorted to pin 4 and pin 5 must be shorted to pin 7. Once this revision is made, the added jumpers need not be removed even though the Ballast is once again inserted.

